



## Adapter cables



# Mindray SPO2 ADAPTER CABLES

Monitor side conn. P/N	Sensor side conn. P/N	Use with sensor	P/N	OEM #	Len.
 CN39	 CN49	Nellcor non-oximax/BCI	DMS0218	0515-30-11221	2.2m
 CN39	 CN49	Nellcor non-oximax/BCI	DMS0218A	Masim tech.	2.2m
 CN39	 CN49	Masim LNCS	DMS0218AM	0010-30-12452	2.2m
 CM5	 CN49	Nellcor non-oximax/BCI	DMS0218B	512A-30-06074	2.2m
 CP5	 CN49	Nellcor non-oximax/BCI	DMS0218C		2.2m
 CP6	 CN49	Nellcor non-oximax/BCI	DMS0218D		2.2m
 CP6R	 CN49	Nellcor non-oximax/BCI	DMS0218E	0010-20-42594	2.2m
 CP6R	 CN49	Nellcor non-oximax/BCI	DMS0218F	Masim tech.	2.2m
 CP6R	 CN49	Masim LNCS	DMS0218FM	0010-30-42602	2.2m
 CP6S	 CN49	Masim LNCS	DMS0218GM	0010-30-42625	2.2m
 CN27	 CN49	Nellcor non-oximax/BCI	DMS0218H	0010-20-42710	2.2m

## Mindray SPO2 ADAPTER CABLES

Monitor side conn. P/N	Sensor side conn. P/N	Use with sensor	P/N	OEM #	Len.
 CN28	 CN49	Nellcor non-oximax/BCI	DMS0218J	Masim tech	2.2m
 CN28	 CN49	Masim LNCS	DMS0218JM	0010-30-42738	2.2m
 CN29	 CN49	Nellcor oximax	DMS0218K	0010-20-42712 Oximax	2.2m
 CP6R	 CN49	Nellcor oximax	DMS 0218M		2.2m
 CP6R	 CN55	Masim Lnop	DMS 0218N	9200-30-10707	2.2m
 CP6T	 CN49	Nellcor oximax	DMS 0218L		2.2m
 CN91	 CN49	Masim MLNCS	DMS 0218P	115-020768-00	2.2m

## DIRECT MEDICAL SOLUTIONS

Address :1116 Chase Ln, Norcross, GA 30093, USA

Web: [directmedicalsolutions.com](http://directmedicalsolutions.com)

Email: [infodirectmedicalsolution@gmail.com](mailto:infodirectmedicalsolution@gmail.com)

Tel: +1 (678) 632-2882

